



**Lycoming At Overhaul 100% Parts & Replacement List \***  
**Engine Model: IO-360-A & C SERIES**

Description	Part Number	Quantity
Engine Gasket Set	SL75441-1	1
Piston Rings	SL3601-SC	4
Piston Pins	SL13444-1	4
Piston Pin Plugs	INC W/PIN	
Exhaust Valves	SL16740A	4
Intake Guides	SL66713A	4
Exhaust Guides	SL75838A	4
Exhaust Valve Retaining Rings	MS13997-3	8
Rocker Assemblies ( '76 Series )	N/A	
Aluminum Push Rods Assemblies ( 235 & 290's )	N/A	
Hydraulic Plunger Assemblies	SL78290	8
Bearing Inserts ( Main ) (Front)	SL13884A	2
Bearing Main (Rear & Intermediate)	SL11020	4
Bearing Inserts ( Connecting Rods)	SL74309A	8
Stressed Bolts & Fasteners:		
Stationary Drive Gear Bolts	N/A	
Camshaft Gear Attaching Bolts	N/A	
Connecting Rod Bolts	SL12596	8
Connecting Rod Nuts	SL12186	8
Crankshaft Flange Bolts	N/A	
Crankshaft Gear Bolt	SL-STD-2213	1
Counterweight Bushings		
Oil Pump Bodies	SL78528	1
Oil Pump Gears	SL18109A-S	1
Washers	A/R	
Washers	A/R	1
Washers	A/R	1
Washers	A/R	1
Washers	A/R	1
Washers		1
Washers	A/R	
Washers	A/R	
Washers	A/R	
Lock Nuts	N/A	
Oil Seal Crankshaft	SL13792	1
Oil Seal Tach Drive	SL14260	1
Oil Seal Vacuum Pump	SL-STD-208	1
Propeller Governor Oil Line Elbows	MS20822-6	1
Propeller Shaft Sleeve Rings	N/A	
Magneto Drive Cushions		
Thermostatic Bypass Valves	SL53E19600	1
Crankshaft Sludge Tubes	N/A	
Circlip	MS16625-2081	1
Circlip	STD-1221	1



**Lycoming At Overhaul 100% Parts & Replacement List \***  
**Engine Model: IO-360-A & C SERIES**

Description	Part Number	Quantity
Lock Plate Crankshaft	SL18639	1
Lock Plate	SL73383	1
All Retaining Rings	N/A	
All Laminated Shims	N/A	
Pinion Shaft Rollers	N/A	
Propeller Shaft Thrust Bearings	N/A	
Supercharger Bearing Oil Seals	N/A	
Cylinder Fin Stabilizers	SL72344	4
Cylinder Fin Stabilizers	SL72343	4
Damaged Ignition Cables	M4004 SLICK	1
Accessory Drive Coupling Springs	N/A	
AC Diaphragm Fuel Pumps	LW15473	1
All V-Brand Couplings	N/A	
All V-Brand Gaskets	N/A	
Engine Hoses Oli Drainback Cylinder	SL-STD-2180	4
All Engine Hose Assemblies		

\* In Accordance with Textron-Lycoming Mandatory Service Bulletin 240R